

# Product change notification THT and SMD LED



20.01.2021

Date	Part-number	Replaced trought part-no.	Merger 01.01.2020 new part-no.	Status (expiring = remaining amount on request)
20.01.2021	Series 104	-	-	no longer available
20.01.2021	Series 108	-	-	no longer available
20.01.2021	108S111R2N40P0	-	-	no longer available
20.01.2021	Series 114	-	-	no longer available
20.01.2021	114S011G2FL2P0	-	-	no longer available
20.01.2021	114S011R2N40P0	-	-	no longer available
20.01.2021	Series 116	-	-	no longer available
20.01.2021	116S011G2G301E	-	-	no longer available
20.01.2021	Series 13C	-	-	no longer available
20.01.2021	13CS00GY2F0	-	-	no longer available
20.01.2021	13CS00G3010	-	-	no longer available
20.01.2021	13CS00G3010	-	-	no longer available
20.01.2021	13CS00G3010	-	-	no longer available
20.01.2021	13CS00R3010	-	-	no longer available
20.01.2021	13CS00R3010	-	-	no longer available
20.01.2021	13CS00R3010	-	-	no longer available
20.01.2021	13CS00Y3010	-	-	no longer available
20.01.2021	13CS00Y3010	-	-	no longer available
20.01.2021	13CS01R3010	-	-	no longer available
20.01.2021	13CS01Y3010	-	-	no longer available
20.01.2021	Series 14C	-	-	no longer available
20.01.2021	14CS00G3010	-	-	no longer available
20.01.2021	14CS00G3010	-	-	no longer available
20.01.2021	14CS00R3010	-	-	no longer available
20.01.2021	14CS00Y3010	-	-	no longer available
20.01.2021	Series 171	-	-	no longer available
20.01.2021	171R3000	-	-	no longer available
20.01.2021	Series 313	-	-	no longer available
20.01.2021	Series 314	-	-	no longer available
20.01.2021	314B01000R1R1D	-	-	no longer available
20.01.2021	Series 318	-	-	no longer available
20.01.2021	318B31010R1G10	-	-	no longer available
20.01.2021	318B11015G1G1D	-	-	no longer available
20.01.2021	318B11015R1R1D	-	-	no longer available
20.01.2021	318B11015R1Y1D	-	-	no longer available
20.01.2021	318B11015Y1Y1D	-	-	no longer available
20.01.2021	318B11010R1Y1D	-	-	no longer available
20.01.2021	Series 614	-	-	no longer available
20.01.2021	6144S1G5M9D	-	-	no longer available
20.01.2021	6144S1R5M9D	-	-	no longer available
20.01.2021	6144B1Y5M9E	-	-	no longer available
20.01.2021	6144S1G5M9B	-	-	no longer available

# Product change notification THT and SMD LED



20.01.2021

Date	Part-number	Replaced trought part-no.	Merger 01.01.2020 new part-no.	Status (expiring = remaining amount on request)
20.01.2021	Series 644	-	-	no longer available
20.01.2021	6144S1Y5M9D	-	-	no longer available
20.01.2021	6444S2Y5M9D	-	-	no longer available
20.01.2021	6444S2Y5M9D	-	-	no longer available
20.01.2021	Serie BA9S	-	-	no longer available
20.01.2021	BA9S-W7B9D	-	-	no longer available
20.01.2021	BA9S-L5W54NBSD01	-	-	no longer available
20.01.2021	BA9S-L5W50NBSD01	-	-	no longer available
20.01.2021	BA9S-L5W50NBSD01	-	-	no longer available
20.01.2021	BA9S-L5W52NBSA01	-	-	no longer available
20.01.2021	BA9S-L5W52NBSB01	-	-	no longer available
20.01.2021	BA9S-L5W52NBSD01	-	-	no longer available
20.01.2021	BA9S-L5W53NBVWD01	-	-	no longer available
20.01.2021	BA9S-L5W53NBVWA01	-	-	no longer available
20.01.2021	BA9S-C2W54NBSD05	-	-	no longer available
20.01.2021	Series E10	-	-	no longer available
20.01.2021	E10-L5W54NBSD01	-	-	no longer available
20.01.2021	E10-L5W54NBSB01	-	-	no longer available
20.01.2021	E10-L5W54NBSA01	-	-	no longer available
20.01.2021	E10-L5W52NBSD01	-	-	no longer available
20.01.2021	E10-L5W50NBSA01	-	-	no longer available
20.01.2021	E10-W7B9D	-	-	no longer available
20.01.2021	Series E14	-	-	no longer available
20.01.2021	Series T5.5	-	-	no longer available
20.01.2021	Series WB	-	-	no longer available
20.01.2021	WB4.6-RF01D-01	-	-	no longer available
20.01.2021	WB-L3W36NBVW	-	-	no longer available
20.01.2021	WB4.6-WF01D-01	-	-	no longer available
20.01.2021	WB4.6-GF01D-01	-	-	no longer available
08.12.2020	Series 102	-	-	no longer available
08.12.2020	102KSJ1A1B38AJ	-	-	no longer available
08.12.2020	102KSJ1B1B38AJ	-	-	no longer available
08.12.2020	102KSJ1G1B38AJ	-	-	no longer available
08.12.2020	102KSJ1R1B38AJ	-	-	no longer available
08.12.2020	102KSJ1R1B38BP	-	-	no longer available
08.12.2020	102RSJ6B13WON342	-	-	no longer available
08.12.2020	102RSJ6B13WON356	-	-	no longer available
08.12.2020	102RSJ6C13WON356	-	-	no longer available
08.12.2020	102RSJ6C14B1G356	-	-	no longer available
08.12.2020	102RSJ6R13WON356	-	-	no longer available
26.10.2020	Series 200	-	-	no longer available
26.10.2020	2001100B1B91GD	-	-	no longer available

# Product change notification THT and SMD LED



20.01.2021

Date	Part-number	Replaced trought part-no.	Merger 01.01.2020 new part-no.	Status (expiring = remaining amount on request)
26.10.2020	200110C1N50JAI55	-	-	no longer available
04.03.2020	314B00000R1G10	-	-	no longer available
04.03.2020	314B01000R1G1A	-	-	no longer available
04.03.2020	314B01000R1R1D	-	-	no longer available
04.03.2020	314B01000R1Y1B	-	-	no longer available
04.03.2020	314B01000R1Y1D	-	-	no longer available
04.03.2020	318B11010R1R1D	-	-	no longer available
04.03.2020	318B11010R1Y1D	-	-	no longer available
04.03.2020	318B11015G1G1D	-	-	no longer available
04.03.2020	318B11015R1R1D	-	-	no longer available
04.03.2020	318B11015R1Y1D	-	-	no longer available
04.03.2020	318B11015Y1Y1D	-	-	no longer available
04.03.2020	318B31010R1G1D	-	-	no longer available
04.03.2020	318B31010R1G10	-	-	no longer available
31.01.2020	SMD-YPLCC-10	-	SLO-230Y-00002	replaced and continued
31.01.2020	SMD-RPLCC-10	-	SLO-230R-00003	replaced and continued
31.01.2020	SMD-NPLCC-10	-	SLO-230N-00003	expiring stock parts
31.01.2020	SMD-GPLCC-10	-	SLO-230G-00004	replaced and continued
31.01.2020	SMD-BPLCC-10	-	SLO-230B-00003	replaced and continued
31.01.2020	L5-W54N-BU	L5-W55N-BVW	SLO-234W-00006	replaced and continued
31.01.2020	L5-W50N-BT	L5-W50N-BVW	SLO-234W-00001	replaced and continued
31.01.2020	L5-R71F	-	SLO-234R-00018	replaced and continued
31.01.2020	L5-G81N-GT	L5-G81N-GUV	SLO-234G-00024	replaced and continued
31.01.2020	L3-Y30Q	n/A	-	no longer available
31.01.2020	L3-W35N-BS	L3-W36N-BVW	SLO-233W-00002	replaced and continued
31.01.2020	L3-W30N-BS	L3-W32N-BVW	SLO-233W-00001	replaced and continued
31.01.2020	L3-R32W	-	SLO-233R-00013	no longer available
31.01.2020	L3-G41N-GT	L3-G41N-GVW	SLO-233G-00014	replaced and continued
31.01.2020	L3-G30Q	n/A	-	no longer available
31.01.2020	L3-B51G-WT	L3-B41G-WS	SLO-233B-00002	no longer available
30.01.2020	L3-G3C2	-	SLO-233G-00004	replaced and continued
27.01.2020	PL6-NL02-G-C8	SZ5-M2-WW-C8 G	-	replaced and continued
03.12.2019	SMD-HX133A-TRB-AG	n/A	-	no longer available
21.11.2019	L3-A300	L3-A300-1	SLO-233A-00002	expiring stock parts
21.11.2019	117MD11A1A300D	-	-	expiring stock parts
21.11.2019	117MD16A2A300D	-	-	expiring stock parts
21.11.2019	117MD16A2A300E	-	-	expiring stock parts
21.11.2019	133R4U1NA3000	-	-	expiring stock parts
21.11.2019	1440S1A300B	-	-	no longer available
21.11.2019	2340S0A300AB	-	-	no longer available
21.11.2019	L3-B311	-	SLO-233B-00001	no longer available
21.11.2019	193S008B1B31DD	n/A	-	no longer available

# Product change notification THT and SMD LED



20.01.2021

Date	Part-number	Replaced trought part-no.	Merger 01.01.2020 new part-no.	Status (expiring = remaining amount on request)
21.11.2019	L3-G3C1	-	SLO-233G-00003	no longer available
21.11.2019	1444B10G3C1B	n/A	-	no longer available
21.11.2019	1444B10G3C1A	n/A	-	no longer available
21.11.2019	134NB1G3C1A	n/A	-	no longer available
21.11.2019	L3-R3FF	-	SLO-233R-00003	expiring stock parts
21.11.2019	L3-R41Q	-	SLO-233R-00016	expiring stock parts
21.11.2019	L3-R3C1	L3-R3C3	SLO-233R-00002	expiring stock parts
21.11.2019	134NB1R3C1A	-	-	expiring stock parts
21.11.2019	1344B10R3C1A	-	-	expiring stock parts
21.11.2019	1340B0R3C2BD	-	-	expiring stock parts
21.11.2019	L3-Y3FF	-	SLO-233Y-00002	expiring stock parts
21.11.2019	L3-Y320	-	SLO-233Y-00010	expiring stock parts
21.11.2019	1447S10Y320E	-	-	expiring stock parts
14.11.2019	L3-G3FF	-	SLO-233G-00005	expiring stock parts
14.11.2019	L3-R32F	-	SLO-233R-00011	expiring stock parts
14.11.2019	148421030R32FZ53	-	-	no longer available
14.11.2019	14820030R32FZ53A	-	-	no longer available
14.11.2019	14820030R32FZ53	-	-	no longer available
14.11.2019	L3-G320	-	SLO-233G-00011	expiring stock parts
14.11.2019	1447S10G320E	-	-	no longer available
14.11.2019	1340B1G320E	-	-	no longer available
07.10.2019	L3-A31B	-	SLO-233A-00004	expiring stock parts
07.10.2019	134R8U1NA31BE	-	-	expiring stock parts
19.09.2019	L5-GG5F	-	SLO-234G-00001	expiring stock parts
19.09.2019	3340S1GG5FD	-	-	no longer available
19.09.2019	3344S1GG5FD	-	-	no longer available
19.09.2019	3350S0GG5FD	-	-	expiring stock parts
19.09.2019	3434B1G1GG5FE	-	-	no longer available
19.09.2019	3550S0GG5FD	-	-	expiring stock parts
19.09.2019	L5-RR5F	-	-	no longer available
19.09.2019	3550S0RR5FD	-	-	no longer available
19.09.2019	3340S1RR5FD	-	-	no longer available
19.09.2019	L5-YY5F	-	SLO-234Y-00001	expiring stock parts
19.09.2019	3344S1YY5FD	-	-	no longer available
13.09.2019	C71Y2210	-	-	no longer available
13.09.2019	C71R2210	-	-	no longer available
13.09.2019	C71G2210	-	-	no longer available
13.09.2019	C71A2210	-	-	no longer available
13.06.2019	SMD-YPLCC-02	-	SLO_230Y-00001	replaced and continued
13.06.2019	SMD-RPLCC-02	SMD-RPLCC-04	SLO-230R-00009	replaced and continued
23.06.2017	L5-R91U	L5-R54U	SLO-234R-00015	replaced and continued
16.02.2016	963xxxx	-	-	no longer available

## Product change notification THT and SMD LED



20.01.2021

Date	Part-number	Replaced trought part-no.	Merger 01.01.2020 new part-no.	Status (expiring = remaining amount on request)
04.12.2015	L5-A5F1	-	-	no longer available
04.12.2015	3350S0A5F10	-	-	no longer available
25.10.2013	NS6W183T	-	-	no longer available
26.08.2013	L5-W602 QRD	-	-	no longer available
26.08.2013	L5-W602 PQD	-	-	no longer available
26.08.2013	L5-W602 PQBC	-	-	no longer available
26.08.2013	L5-W601S STD-T	-	-	no longer available
26.08.2013	L5-W601 STD	-	-	no longer available
26.08.2013	L5-W601 STBC	-	-	no longer available
26.08.2013	L5-N603 STEF	-	-	no longer available
26.08.2013	L5-N603 SF	-	-	no longer available
26.08.2013	L5-N603 QREF	-	-	no longer available
17.05.2013	L5-W52N-BS	L5-W53N-BVW	SLO-234W-00002	replaced and continued
21.12.2012	L3-G51N-GT	L3-G51N-GUV	SLO-233G-00015	replaced and continued
21.11.2012	L5-W54N-BS	L5-W55N-BVW	SLO-234W-00006	replaced and continued